

Time & Material Radio Repairs

End of Repairs Notification

In 2013 cancellation notices were issued for the GP ATEX radio family, confirming End of Sales for GP340Ex and GP380Ex, GP680Ex and GP580Ex ATEX radios. As key components required to service these radio models are no longer available and cannot be sourced due to the high ATEX certification restrictions on repair piece parts along with the need for any part to be certified and approved by DEKRA, we will no longer be able to service these devices. Therefore with immediate effect Motorola Solutions will cease offering repairs on GP ATEX radios; GP340 Ex, GP380 Ex ATEX, GP680 Ex and GP580 Ex ATEX radios. Partners that may have sent any of the aforementioned GP ATEX radio devices to the EMEA Repair Center will be contacted by MSI staff shortly.